

CAUTION
Bonding between metallic
conduit connections is not
automatic.
Separate bonding must be
provided.

Grid Industries, Inc.
11000 SOUTHWEST
To maintain UL
listing, all
equipment must be
approved. Cover
access from the
No. 01 2128443

UL
LISTED
INDUSTRIAL
CONTROL
PANELS
ENCLOSURE